

Inspection Photos  
Location Name: TAMBURELLI 33-3  
API #: 05-071-6615  
Insp. Doc. # 695100271



Colorado Oil & Gas Conservation Commission  
37.19787, -104.65612, 2054.0m, 61°  
2019/03/06 14:13:11



Colorado Oil & Gas Conservation Commission  
37.1979, -104.65597, 2071.0m, 103°  
2019/03/06 14:13:44

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN/METER HOUSE/EMERGENCY CONTACT  
NUMBER IS INACCURATE

## Inspection Photos

Location Name: TAMBURELLI 33-3

API #: 05-071-6615

Insp. Doc. # 695100271



Colorado Oil & Gas Conservation Commission  
37.19789, -104.65594, 2071.0m, 273°  
2019/03/06 14:15:51



Colorado Oil & Gas Conservation Commission  
37.19789, -104.65594, 2070.0m, 277°  
2019/03/06 14:15:45

**PHOTO 3: PRODUCED WATER DRIPPING FROM SEPARATOR TO THE GROUND**

**PHOTO 4: PRODUCED WATER DRIPPING FROM SEPARATOR TO THE GROUND**



**Inspection Photos**  
**Location Name: TAMBURELLI 33-3**  
**API #: 05-071-6615**  
**Insp. Doc. # 695100271**



Colorado Oil & Gas Conservation Commission  
37.19799, -104.6557, 2067.0m, 55°  
2019/03/06 14:17:13




Colorado Oil & Gas Conservation Commission  
37.19799, -104.6557, 2067.0m, 68°  
2019/03/06 14:16:57

**PHOTO 7: TRASH & DEBREE INSIDE PRIME MOVER HOUSE**

**PHOTO 8: TRASH & DEBREE INSIDE PRIME MOVER HOUSE**

Inspection Photos  
Location Name: TAMBURELLI 33-3  
API #: 05-071-6615  
Insp. Doc. # 695100271



**PHOTO 9: CALIBRATION REPORT IS PAST DUE/ OVER ONE YEAR SINCE LAST CALIBRATION.**