

## Inspection Photos

Location Name: AC McLAUGHLIN SENIOR 61

Location ID: 05-103-05467

Inspection: 679703259



Photo 1. Location looking east.



Photo 2. Well head sign incorrect operator.

