

Inspection Photos

Location Name: McLAUGHLIN SR 17-33

Location ID: 05-103-40158

Inspection: 679703265



Photo 1. Location looking southeast.



Photo 2. Tank battery.



Inspection Photos

Location Name: McLAUGHLIN SR 17-33

Location ID: 05-103-40158

Inspection: 679703265



Photo 3. Container stored next to wellhead.



Photo 4. Sign missing nearest public access road, Hwy 64.