

Inspection Photos

API: 05-071-07927

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/1/2019

Inspection Photos



Photo 1. Facing northeast toward the location.

Inspection Photos



Photo 2. The location has not been recontoured and reclaimed..

Inspection Photos



Photo 3. Facing toward the fill slope at the west side of the location.

Inspection Photos



Photo 4. Facing toward the cut slope at the north side of the location.

Inspection Photos



Photo 5. Facing back toward the south at the location.