

Inspection Photos

Location Name: HESTER-67N66W /31SWNW

Location #: 306743



Photo #1

Hester 31-23 (05-123-25183) Wellsite

Plugged & Abandoned | PA

**Casing NOT Cut & Capped | No temporary Safety Cap
from prev. FIR**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HESTER-67N66W /31SWNW

Location #: 306743



Photo #2

Hester 31-23 Wellsite

Plugged & Abandoned | PA

Casing Cut & Capped | Reclamation in process



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources