

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/07/2019

Submitted Date:

03/07/2019

Document Number:

696100407

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
305320 \_\_\_\_\_ Evins, Bret \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276532	WELL	SI	09/01/2015	GW	123-22797	WEBER 6-13	SI

**General Comment:**

This is a WELL &amp; BATTERY Inspection.

Well is SI &amp; LOTO.

Battery &amp; ALL equipment is Shut-down.

1 - Corrective Action identified.

1.) SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See photo #1.

Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Produced H2O vault capacity label is fading. Consider replacing.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See photo #1.		
Corrective Action:	Install orange decommission tag at wellsite. Comply with Doc #401474555 (NOBLE).	Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by metal berms.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	ECD scrubber		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Controls crude oil tanks VOCs Pilots: OFF   Shut-down.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.516489,-104.817566
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms w/ produced H2O vault.				
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	
-----------	--

Other (Content)	
Other (Capacity) 48 Bbls.	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Shares berms w/ crude oil tank.				
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 276532 Type: WELL API Number: 123-22797 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Observed well SI & LOTO.  
COGCC records indicate SI since 09/2015.  
Orange decommission tag for SI/TA status not present at wellsite. No current MIT on record.  
SI/TA well per variance Doc #401474555. (NOBLE).

Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100408	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755924">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755924</a>