

Inspection Photos
Location Name: PARK MOUNTAIN 10-7
Location ID: 05-103-10024
Inspection: 679703279



Photo 1. Location looking north.



Photo 2. Excavated hole on edge of location.

Inspection Photos

Location Name: PARK MOUNTAIN 10-7

Location ID: 05-103-10024

Inspection: 679703279



Photo 3. Edge of location.



Photo 4. Sign missing nearest public road, CR 109.

