

Inspection Photos

Location Name: PARK MOUNTAIN 31-7

Location ID: 05-103-09756

Inspection: 679703281



Photo 1. Location.



Photo 2. Sign without nearest public rd, CR 109.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: PARK MOUNTAIN 31-7
Location ID: 05-103-09756
Inspection: 679703281



Photo 3. Unused barrel without label.



Photo 4. Unused barrel.