

Construction and Storm Water Inspection

March 1, 2019

Operator: NGL WATER SOLUTIONS DJ LLC - 10373

Location ID: 456888

Inspection Document #: 674902650

Weld County, CO

SWNE Section 30 T1N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 1. Photo taken from the northwestern perimeter of the location, facing South. Photo illustrates the installed silt fence BMP is not in proper functioning condition.



Photo 2. Photo taken from the northwestern perimeter of the location, facing Southeast. See comments from Photo 1. There is also a ditch and berm BMP installed around the perimeter. However there are no sediment traps with stabilized outlets observed on location at the time of inspection.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 3. Photo taken from the western perimeter of the location, facing Northeast. Photo depicts the drilling rig is on location and no sediment traps with stabilized outlets were observed on location at the time of inspection.



Photo 4. Photo taken from the southwestern perimeter of the location, facing East. See comments from Photos 1 and 2.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 5. Photo taken from the access road off CR 27, facing Southeast. The access road has been rerouted to the south due to an apparent culvert failure on the previous access road entrance.



Photo 6. Photo taken from the access road off CR 27 looking into where the original entrance was, facing North. See comments from Photo 5.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 7. Photo taken from the access road off CR 27, facing East. Appears Operator has installed tracking pads and gravel to potentially limit tracking onto the county road.



Photo 8. Photo taken from the access road off CR 27, facing South. Photo depicts the three new culverts installed.