

Inspection Photos

Location Name: LINDBLAD-67N67W /25SESW

Location #: 310411



Photo #1

Lindblad 25-34 (05-123-26371) Wellsite

Temporarily Abandoned | TA



Photo #2

Lindblad 25-34 Battery

Shut-down

