

Inspection Photos

Location Name: TJADEN-67N67W /36NENE

Location #: 306003



Photo #1

Tjaden 36-11 Wellsite
Unused Equipment
from prev. FIR



Photo #2

Tjaden 36-11 (05-123-23814) Wellsite
Temporarily Abandoned | TA - LOTO
Unused Equipment – Removed
Orange Decommission tag - Present



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TJADEN-67N67W /36NENE

Location #: 306003



Photo #3

Tjaden 36-11 Abandoned Battery site

Unused Equipment

Gas meter run, Signs

