

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2019

Submitted Date:

03/08/2019

Document Number:

696100419**FIELD INSPECTION FORM**Loc ID 423085 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423098	WELL	PR	11/01/2018	OW	123-33500	LINDBLAD PC MM 25-15	TA

**General Comment:**

This is a WELL & BATTERY Inspection.  
Well is TA & LOTO.  
Battery & ALL equipment is Shut-down.

2 - Corrective Actions identified.

1.) Unused Equipment at wellsite & Gas meter run area. Refer to Rule 603.f for guidance (30 Days). See photos #1, #3.  
Remove unused equipment at wellsite & gas meter run area. Comply w/ Rule 603.f.

2.) SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See photo #1.  
No current MIT on record.

Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See photo #1. No current MIT on record.		
Corrective Action:	Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).	Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment at wellsite & Gas meter run area. Refer to Rule 603.f for guidance (30 Days). See photos #1, #3.		
Corrective Action:	Remove unused equipment at wellsite & gas meter run area. Comply w/ Rule 603.f.	Date:	04/08/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment: ECD scrubber			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment: Controls crude oil tanks VOCs Pilots: OFF   Shut-down.			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Bradenhead appears plumbed to surface.			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ crude oil tank.				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.538163,-104.837437	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">Shares berms w/ produced H2O vault.</a>					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	423098	Type:	WELL	API Number:	123-33500	Status:	PR	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Observed well TA &amp; LOTO. Well disconnected from flowline. COGCC records indicate SI since 12/2018. No current MIT on record. Orange Decommission Tag is NOT present. SI/TA well per variance Doc #401474555. (NOBLE).</div>							
Corrective Action:							Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100420	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4756639">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4756639</a>