

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2019

Submitted Date:

03/08/2019

Document Number:

696100421**FIELD INSPECTION FORM**Loc ID 306003 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284464	WELL	SI	06/01/2018	OW	123-23814	TJADEN 36-11	TA

**General Comment:**

This is a WELL & ABANDONED BATTERY Inspection.  
Well is TA.  
Battery is Abandoned & ALL equipment except gas meter run & signs has been removed.  
Abandoned Battery SE corner GPS coordinates: 40.536093, -104.832580  
Follow-up to FIR #691300373 dated 07/12/2018.  
1 of 1 Corrective Actions from previous FIR has been addressed.  
1.) LTSI well had no MIT on record.  
No orange decommission tag present per SI/TA well per variance Doc #401474555. (NOBLE).  
Orange tag is now posted. See photos #1-2.  
2.) Unused equipment noted at wellsite. Unused equipment at wellsite has been removed. See photos #1-2.

1-Corrective Action identified on this FIR.  
1.) Unused gas meter run & signs at Abandoned Battery site.  
Refer to Rule 603.f for guidance when machinery required to remove equipment (90 Days). See photo #3.  
Remove unused gas meter run & signs at Battery site. Comply w/ Rule 603.f.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	LTSI well had no MIT on record. From prior FIR: No orange decommission tag present per SI/TA well per variance Doc #401474555. (NOBLE). Orange tag is now posted. See photos #1-2.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment noted at wellsite from prior FIR. Unused equipment at wellsite has been removed. See photos #1-2.		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	Unused gas meter run & signs at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment (90 Days). See photo #3. Remove unused gas meter run & signs at Battery site. Comply w/ Rule 603.f.		
Corrective Action:	Remove unused gas meter run & signs at Battery site. Comply w/ Rule 603.f.		Date: 06/06/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No <input type="checkbox"/>			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Other	# 1		corrective date
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:			Date:

Type: Other	# 1		
Comment:	Wellhead w/ master valve, casing head & valves.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	284464	Type:	WELL	API Number:	123-23814	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Observed well TA &amp; LOTO. Battery has been abandoned with all production equipment removed. SI/TA well per variance Doc #401474555. (NOBLE). Orange decommission tag is posted.</div>							
Corrective Action:							Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100422	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4756640">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4756640</a>