

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401966201

Date Received:

03/08/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 687903855

Inspection Date: 03/07/2019

FIR Submit Date: 03/07/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333076

Location Name: ALLISON UNIT-N32N7W Number: 24SWNE County: LA PLATA

Qtrqtr: SWNE Sec: 24 Twp: 32N Range: 7W Meridian: N

Latitude: 37.003360 Longitude: -107.558700

FACILITY - API Number: 05-067- -00 Facility ID: 292896

Facility Name: ALLISON UNIT Number: 147T

Qtrqtr: SWNE Sec: 24 Twp: 32N Range: 7W Meridian: N

Latitude: 37.003360 Longitude: -107.558700

CORRECTIVE ACTIONS:

1 CA# 123022

Corrective Action: Please comply with Rule 605.e. and 905.b.

Date: 03/10/2019

Response: CA COMPLETED

Date of Completion: 03/08/2019

Operator Comment: The surface water within the secodary containment has been cleared out. See attached photos.

COGCC Decision: _____

Date: 04/08/2019

Date of Completion: 03/08/2019

Th unused equipment on and around pump jack has been cleared. The unused batteries and old ball valve have been removed. See attached photos

Date: 04/08/2019

Date of Completion: 03/08/2019

Th used rags and soaker pads on or around pump jack has been cleared. See attached photos

Comment:

Signed:

Date: 3/8/2019 1:30:40 PM

<u>Document Number</u>	<u>Description</u>
401966240	Floating Tank Resolved Photo
401966242	Clean Up Photo
401966244	Sign on ground resolved photo
401966246	Unused equip resolved photo
401966248	Unused equip resolved photo

Page 2 of 2