

Inspection Photos  
Location Name: Schmidt #2  
API: 05-083-06256



Emergency contact number has been updated.



~900 gallon fiberglass tank no longer in use.

**Inspection Photos**  
**Location Name: Schmidt #2**  
**API: 05-083-06256**



**Fiberglass tanks have both been removed from service.  
Remove unused equipment from location.**

**Pit Facility ID #112977 upgrades are complete and pit is in  
service once again.**

**Inspection Photos**  
**Location Name: Schmidt #2**  
**API: 05-083-06256**



**Pit Facility ID #112977 has been returned to service.  
Equipment blew down to pit during this inspection.**



**Remove unused liner from location.**

**Inspection Photos**  
**Location Name: Schmidt #2**  
**API: 05-083-06256**



**Pit is fenced and netted.**



**Ensure stability of slopes along north and west sides of pit.**