

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2019

Submitted Date:

03/08/2019

Document Number:

689303486**FIELD INSPECTION FORM**Loc ID 413567 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|------------------------|------------------------|
| Ghan, Scott | 970-744-8128 | sghan@vnrenergy.com | SR. EH&S |
| Aaron, Axelson | 230-0926 | aaxelson@vnrenergy.com | Sr. Production Foreman |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 412774 | WELL | PR | 06/24/2010 | GW | 045-18595 | THARP 41D-23-692 | PR |
| 412775 | WELL | PR | 07/13/2010 | GW | 045-18596 | THARP 44C-14-692 | PR |
| 412776 | WELL | PR | 06/14/2010 | GW | 045-18597 | THARP 44B-14-692 | PR |
| 412777 | WELL | PR | 07/26/2010 | GW | 045-18598 | THARP 44A-14-692 | PR |
| 412778 | WELL | PR | 02/01/2016 | GW | 045-18599 | THARP 44D-14-692 | PR |
| 412779 | WELL | PR | 06/14/2010 | GW | 045-18600 | THARP 11A-24-692 | PR |
| 412780 | WELL | PR | 06/01/2010 | GW | 045-18601 | THARP 11B-24-692 | PR |
| 412781 | WELL | PR | 06/01/2010 | GW | 045-18602 | THARP 11C-24-692 | PR |
| 412782 | WELL | PR | 06/01/2010 | GW | 045-18603 | THARP 11D-24-692 | PR |
| 412783 | WELL | PR | 07/26/2010 | GW | 045-18604 | THARP 14A-13-692 | PR |
| 412784 | WELL | PR | 07/26/2010 | GW | 045-18605 | THARP 14B-13-692 | PR |
| 412785 | WELL | PR | 07/26/2010 | GW | 045-18606 | THARP 14C-13-692 | PR |
| 412786 | WELL | PR | 07/13/2010 | GW | 045-18607 | THARP 14D-13-692 | PR |
| 412787 | WELL | PR | 06/14/2010 | GW | 045-18608 | THARP 41A-23-692 | PR |
| 412788 | WELL | PR | 06/14/2010 | GW | 045-18609 | THARP 41B-23-692 | PR |
| 412789 | WELL | PR | 06/24/2010 | GW | 045-18610 | THARP 41C-23-692 | PR |

General Comment:

This is a follow up inspection from Doc# 689303404. Required Corrective Action (s) items noted in previous inspections have been satisfied.

Equipment inventory has not changed on location.

| Inspected Facilities | | | | | | | | | |
|-----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 412774 | Type: | WELL | API Number: | 045-18595 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412775 | Type: | WELL | API Number: | 045-18596 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412776 | Type: | WELL | API Number: | 045-18597 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412777 | Type: | WELL | API Number: | 045-18598 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412778 | Type: | WELL | API Number: | 045-18599 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412779 | Type: | WELL | API Number: | 045-18600 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412780 | Type: | WELL | API Number: | 045-18601 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 412781 | Type: | WELL | API Number: | 045-18602 | Status: | PR | Insp. Status: | PR |

| <u>Producing Well</u> | | | | |
|-----------------------|---------------------------------|-------|------|---|
| Comment: | Well Producing on plunger lift. | | | |
| Corrective Action: | | Date: | | |
| Facility ID: | 412782 | Type: | WELL | API Number: 045-18603 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Well Producing on plunger lift. | | | |
| Corrective Action: | | Date: | | |
| Facility ID: | 412783 | Type: | WELL | API Number: 045-18604 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Well Producing on plunger lift. | | | |
| Corrective Action: | | Date: | | |
| Facility ID: | 412784 | Type: | WELL | API Number: 045-18605 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Well Producing on plunger lift. | | | |
| Corrective Action: | | Date: | | |
| Facility ID: | 412785 | Type: | WELL | API Number: 045-18606 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Well Producing on plunger lift. | | | |
| Corrective Action: | | Date: | | |
| Facility ID: | 412786 | Type: | WELL | API Number: 045-18607 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Well Producing on plunger lift. | | | |
| Corrective Action: | | Date: | | |
| Facility ID: | 412787 | Type: | WELL | API Number: 045-18608 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Well Producing on plunger lift. | | | |
| Corrective Action: | | Date: | | |
| Facility ID: | 412788 | Type: | WELL | API Number: 045-18609 Status: PR Insp. Status: PR |
| <u>Producing Well</u> | | | | |
| Comment: | Well Producing on plunger lift. | | | |

| | | | |
|---|---|-------|--|
| Corrective Action: | | Date: | |
| Facility ID: <u>412789</u> Type: <u>WELL</u> API Number: <u>045-18610</u> Status: <u>PR</u> Insp. Status: <u>PR</u> | | | |
| <u>Producing Well</u> | | | |
| Comment: | Well Producing on plunger lift. | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | | | | |
| Ditches | | | | | | |
| Sediment Traps | | | | | | |
| | | Ditches | | | | |
| | | Compaction | | | | |
| Compaction | | | | | | |
| Berms | | | | | | |

Comment: Corrective Action: Date:
Pits: ☒ NO SURFACE INDICATION OF PIT
Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 689303487 | Inspection photo 689303487 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4757356 |