

Inspection Photos
Location Name: ANDERSON-66N66W /10SENE
Location #: 306516



Colorado Oil & Gas Conservation Commission
40.50412, -104.75656, 1463.0m, 303°
2019/03/08 03:49:53 PM

Photo #1

Anderson 42-10 (05-123-24819) Wellsite

Temporarily Abandoned | TA

Unused Equipment



Colorado Oil & Gas Conservation Commission
40.50309, -104.75886, 1470.0m, 286°
2019/03/08 03:58:53 PM

Photo #2

Anderson 31-10, 32-10, 42-10 Battery site