

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/01/2019

Submitted Date:

03/01/2019

Document Number:

689702763

FIELD INSPECTION FORM

Loc ID 335667	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 19 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282296	WELL	PR	08/03/2006	GW	045-11726	N PARACHUTE WF06C-23 F23596	PR
291476	WELL	PR	01/31/2009	GW	045-14383	N PARACHUTE WF12D-23 F23596	PR
291501	WELL	PR	07/31/2008	GW	045-14427	N PARACHUTE WF14C-23 F23596	PR
291502	WELL	PR	07/23/2007	GW	045-14426	N PARACHUTE WF15A-23 F23596	PR
291503	WELL	PR	01/31/2009	GW	045-14425	N PARACHUTE WF05C-23 F23596	PR
291505	WELL	PR	02/01/2012	GW	045-14423	N PARACHUTE WF11D-23 F23596	PR
291506	WELL	PR	07/08/2009	GW	045-14422	N PARACHUTE WF06D-23 F23596	PR
291508	WELL	PR	04/11/2012	GW	045-14421	N. PARACHUTE WF 14A- 23F23596	PR
291512	WELL	PR	03/01/2009	GW	045-14419	N PARACHUTE WF12A-23 F23596	PR
291514	WELL	PR	07/23/2007	GW	045-14418	N PARACHUTE WF14B-23 F23596	PR
291523	WELL	AL	05/27/2011	LO	045-14416	ENCANA RPW 411-23-596	AL
291525	WELL	PR	01/01/2009	GW	045-14414	N PARACHUTE WF11B-23 F23596	PR
291527	WELL	PR	07/23/2007	GW	045-14412	N PARACHUTE WF11A-23 F23596	PR
291529	WELL	PR	01/19/2009	GW	045-14410	N PARACHUTE WF12B-23 F23596	PR

291530	WELL	PR	04/01/2012	GW	045-14408	N PARACHUTE WF11C-23 F23596	PR
--------	------	----	------------	----	-----------	--------------------------------	----

General Comment:

[Routine FIU General Field Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No NFPA sticker on 1 tank and unlegible sticker on another.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	05/03/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 15		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	282296	Type:	WELL	API Number:	045-11726	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291476	Type:	WELL	API Number:	045-14383	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291501	Type:	WELL	API Number:	045-14427	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291502	Type:	WELL	API Number:	045-14426	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291503	Type:	WELL	API Number:	045-14425	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291505	Type:	WELL	API Number:	045-14423	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291506	Type:	WELL	API Number:	045-14422	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	291508	Type:	WELL	API Number:	045-14421	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 291512	Type: WELL	API Number: 045-14419	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291514	Type: WELL	API Number: 045-14418	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291523	Type: WELL	API Number: 045-14416	Status: AL	Insp. Status: AL
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291525	Type: WELL	API Number: 045-14414	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291527	Type: WELL	API Number: 045-14412	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291529	Type: WELL	API Number: 045-14410	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291530	Type: WELL	API Number: 045-14408	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Culverts	Pass			
Berms	Pass					
		Ditches	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401957965	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751192
689702764	Inspection 689702763 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751187