

# Construction and Stormwater Inspection

February 28, 2019

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 461838

Inspection Document #: 682404603

Weld County, CO

NWNW Section 33 T8N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Colorado Rivers Pad  
Location ID: 461838



**Photo 1.** Photo taken from the entrance of location, facing West. Photo illustrates Operator sign.



**Photo 2.** Photo taken from the entrance of location, facing West. Photo illustrates access road in-process of being constructed. Operator salvaged and stored topsoil from the access.

Inspection Photos  
Location Name: Colorado Rivers Pad  
Location ID: 461838



**Photo 3.** Photo taken from the northeastern perimeter of location, facing South. Photo illustrates a ditch and berm BMP installed around the Location. Operator shall stabilize the berm BMP, as an unconsolidated berm BMP is not a proper functioning BMP. Operator indicated that the berm would be stabilized the day of this inspection.



**Photo 4.** Photo taken from the southern perimeter of location, facing West. Photo illustrates topsoil from the Location.

Inspection Photos  
Location Name: Colorado Rivers Pad  
Location ID: 461838



**Photo 5.** Photo taken from the western perimeter of the location, facing East. Photo illustrates Operator in-process of salvaging topsoil.



**Photo 6.** Photo taken from the northern perimeter of location, facing East. Photo illustrates topsoil from the access road.