

Inspection Photos
Location Name: WEBER-66N66W /26NESE
Location #: 319160



Colorado Oil & Gas Conservation Commission
40.45832, -104.73815, 1413.0m, 270°
2019/03/11 11:52:28 AM

Photo #1
Weber 1-26 (05-123-10805) Wellsite
Temporarily Abandoned | TA
Unused Equipment



Colorado Oil & Gas Conservation Commission
40.45819, -104.73839, 1418.0m, 337°
2019/03/11 11:55:33 AM

Photo #2
Weber 1-26 Battery
Shut-down

Inspection Photos

Location Name: WEBER-66N66W /26NESE

Location #: 319160



Photo #3

Weber 1-26 Gas meter run

Unused Equipment

Automation controls

