

Inspection Photos  
Location Name: Stromberger 2-12  
Location ID: 318529



#1 Location view



#2 Load Line on Production Tank  
**Comply with 605.d**

Inspection Photos  
Location Name: Stromberger 2-12  
Location ID: 318529



**#3 Broken Master Valve**  
**Comply W/ 605.d**



**#4 Signage Emergency Contact**  
**Comply w/ 210.b**