

Final Reclamation and Stormwater Inspection

March 1, 2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 305716

Inspection Document #: 674902637

Weld County, CO

NWSE Section 21 T2N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NOBLE ENERGY INC /2N64W21
Location ID: 305716



Photo 1. Photo taken from the access road, facing South. Appears the Operator recently completed reclamation activities with drill seed rows and straw crimped mulch.



Photo 2. Photo taken from the access road, facing South. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC /2N64W21

Location ID: 305716



Photo 3. Photo taken from the facility, facing West. See comments from Photo 1.



Photo 4. Photo taken from the facility, facing South. See comments from Photo 1.

Inspection Photos
Location Name: NOBLE ENERGY INC /2N64W21
Location ID: 305716



Photo 5. Photo taken from the facility, facing West. See comments from Photo 1.



Photo 6. Photo taken from the facility, facing North. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY INC /2N64W21

Location ID: 305716



Photo 7. Photo taken from the location, facing West. See comments from Photo 1.



Photo 8. Photo taken from the location, facing North. See comments from Photo 1.