

## Inspection Photos

Location Name: Federal Macaw 33-1 Location ID 330960

Inspection Date: 3/8/2019



Photo 1 – Pit netting and berms improved, weeds removed.



Photo 2 – Secondary containment around skim tank



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources