

Inspection Photos
Location Name: Piland 15-3
Location ID: 320187



Photo 1 WH unused equipment 55 gal drum



Photo 2 TNK BTRY load lines not bull plugged

Inspection Photos
Location Name: Piland 15-3
Location ID: 320187



Photo 3 Meter run and separator. Unused equipment 55gal drum and meter run box. Unused unmarked 2"risers.




Photo 4 TNK BTRY load lines not bull plugged