

**Inspection Photos**  
**Location Name: Piland #4**  
**Location ID: 319963**



**Photo 1 PU**



**Photo 2 Stained soil and gear box has leak (mechanical issues)**

**Inspection Photos**  
**Location Name: Piland #4**  
**Location ID: 319963**



**Photo 3 Stained soil inside PU motor house**