

Inspection Photos
Location Name: Gary State #36-16
Location ID: 320051




Photo 1 WH All production equipment has been removed from well. Unused equipment: tubing on location



Photo 2 TNK BTRY Weeds

Inspection Photos
Location Name: Gary State #36-16
Location ID: 320051




Photo 3 unused equipment separator house separator has been removed. Unused, unmarked risers and weeds



Photo 4 TNK BTRY Weeds

Inspection Photos
Location Name: Gary State #36-16
Location ID: 320051



Photo 5 TNK BTRY Weeds



Photo 6 Sales line LOTO