

Inspection Photos
Location Name: Farm Ranch exploration #3
Location ID: 320067



Photo 1 PU and WH



Photo 2 stained soil removed around PU