

Inspection Photos
Location Name: MILNE-66N65W /18NENE
Location #: 323272



Photo #1
Milne #4 (05-123-12793) Wellsite
Shut-In | SI
Incorrect Emergency number posted



Photo #2
Milne #4 Battery
Shut-down

Inspection Photos

Location Name: MILNE-66N65W /18NENE

Location #: 323272



Photo #3

Milne #4 Battery

Produced H2O vault

Capacity NOT posted

