



Photo#1:

There is No EVIDENCE of the DA Well on the edge of the Active Location..

February 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Kenny KO DA Stagner API#103-07425