

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/12/2019

Submitted Date:

03/13/2019

Document Number:

682600646

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96340
Name of Operator: WIEPKING-FULLERTON ENERGY LLC
Address: 96 GLENMOOR LN
City: ENGLEWOOD State: CO Zip: 80113

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Halde, Kerry	719-346-0653	haldeoil@hotmail.com	
Herian, Tim	(316) 655-9200	therian1@cox.net	All Inspections
Shalberg, Greg	719-688-3547	gregshalberg@aol.com	all inspections
Boone, Linda	(720) 271-8605	LDBoonePar@aol.com	All Inspections

General Comment:

The Aloha Mula 16 off location flowline experienced a pipeline failure on or about 1 pm on Sunday, March 10th, approximately halfway between the wellhead and the tank battery. Spill location is 39.162861, -103.598569. Spill flowed south on surface. Operator has repaired leak and is in the process of removing contaminated soil.

Operator shall submit a Form 27 Remediation to area Environmental Protection Specialist by April 1st, 2019.

Inspection found no impact to surface water.

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: 20

Comment: Operator reported spill of crude oil from pipeline rupture. Spill volume estimated by inspector.

Corrective Action: By April 1, 2019, submit a Form 27 Site Investigation and Remediation Workplan with a proposed workplan and timeline for remediation of this release. Date: 04/01/2019

Reportable: YES GPS: Lat 39.162861 Long -103.598569

Proximity to Surface Water: 9200 Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600647	COGCC Spill Map	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4761928
682600648	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4761930