

Inspection Photos
Operator: Incremental Oil and Gas
Location/API #: 043-06210
Date: 2/27/2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing within portions of the interim reclamation areas, however sparse areas remain.



Photo 3. View of the eastern project area from the northeastern corner facing southward.