

# Construction and Stormwater Inspection

March 07, 2019

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 455456

Inspection Document #: 682404609

Weld County, CO

NWNE Section 18 T7N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: EAST AULT 18-C PAD  
Location ID: 455456



**Photo 1.** Photo taken from the northwest perimeter of the location, facing East. Photo illustrates a ditch and berm BMP which has been installed around the entire perimeter of the location.



**Photo 2.** Photo taken from the entrance of the location, facing Northwest. Truck traffic tracked out during the inspection. Operator immediately called in a street sweeper which was nearby at the Iceman location.