

Well Name : Brink S2

API # : 001-09363



Photo 1: Third tank after cleaning and curved tank squeegee for cleaning walls of tank.



Photo 2: Two vertical heater treaters in building

Well Name : Brink S2

API # : 001-09363



Photo 3: Vertical heater 1 treater in building.



Photo 4: Inside of vertical heater 1 treater after cleaning.

Well Name : Brink S2

API # : 001-09363



Photo 5: Vertical heater 2 treater in building.



Photo 6: Inside of vertical heater 2 treater after cleaning.

Well Name : Brink S2

API # : 001-09363



Photo 7: Horizontal separator in building with vac truck hose connected to drain. Note sight glass showing fluid levels (oil and water) in separator.



Photo 8: 130 Bbl vac truck. This was load #2.