

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401970475
Date Received:
03/12/2019

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10669
Name of Operator: NICKEL ROAD OPERATING LLC
Address: 600 17TH STREET #610S
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
JENNIFER LIND 303-406-1117 JENNIFER.LIND@NICKELROADOPERATING.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404468
Inspection Date: 01/28/2019 FIR Submit Date: 01/29/2019 FIR Status:

Inspected Operator Information:

Company Name: NICKEL ROAD OPERATING LLC Company Number: 10669
Address: 600 17TH STREET #610S
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 454899

Location Name: DRAKE PAD Number: County:
Qtrqr: NWSE Sec: 12 Twp: 7N Range: 67W Meridian: 6
Latitude: 40.588176 Longitude: -104.838093

FACILITY - API Number: 05-123-00 Facility ID: 454899

Facility Name: DRAKE PAD Number:
Qtrqr: NWSE Sec: 12 Twp: 7N Range: 67W Meridian: 6
Latitude: 40.588176 Longitude: -104.838093

CORRECTIVE ACTIONS:

1 CA# 122083

Corrective Action: Per Rule 805.c., Operator shall control fugitive dust caused by their operations. The corrective date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 01/28/2019

Response: CA COMPLETED Date of Completion: 01/29/2019

Operator Comment: Following receipt of inspection report on 1/29/19, Nickel Road immediately had dirt work contractor onsite contact water truck company to ensure a water-truck was available on-call should pad and weather conditions warrant use. Water truck will remain on call throughout operations at the location. Additionally, the pad location surface was gravelled following the date of this inspection (gravelling complete on 2/8/19) and vehicle tracking control was installed (vehicle tracking install complete on 2/11/19) both assisting in the mitigation of dust conditions. Finally, Nickel Road has plans in place to hydroseed all slopes for stabilization and weed prevention purposes

during the Spring, 2019 growing season. Nickel Road has maintained compliance since the 1/28/19 inspection and will continue to maintain compliance with Rule 805.c.

COGCC Decision: Approved

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received.
On February 21, 2019, Field Inspection Report Doc. #682404574 confirms the well pad has been stabilized with gravel, as stated in the Operator response comment.

OPERATOR COMMENT AND SUBMITTAL

Comment: FIR Resolution submitted in response to Doc #682404468. See detailed response on "Corrective Actions & Responses" tab.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: JENNIFER LIND Signed: _____

Title: REG & ENV MANAGER Date: 3/12/2019 3:35:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401970475	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files