


IMAGE COURTESY OF GOOGLE EARTH 2017

LEGEND

- REMEDIATION WELL
- ⊗ MONITORING WELL
- ⊗ DESTROYED MONITORING WELL
- M METER HOUSE
- ↑ SURVEYED GROUNDWATER FLOW DIRECTION
- ↑ SURFACE WATER FLOW DIRECTION
- RELATIVE GROUNDWATER ELEVATION CONTOUR
CONTOUR INTERVAL = 0.50 FEET
GRADIENT = 0.01 FEET/FOOT

- FENCE
- EXCAVATION EXTENT
- BERM



GROUNDWATER ELEVATIONS WERE MEASURED ON DECEMBER 14, 2018.
NM: NOT MEASURED

FIGURE 2
GROUNDWATER ELEVATION CONTOUR MAP
 DUBACH 16-4, THESING 9-4
 NESE SEC 4-T3N-R66W
 WELD COUNTY, COLORADO
 KERR-MCGEE OIL & GAS ONSHORE LP

