

Inspection Photos
Location Name: KNOX-65N67W /3SWNE
Location #: 331406



Photo #1
Knox 32-3 (05-123-20645) Wellsite
Shut-In | SI – LOTO
from prior FIR



Photo #2
Knox 32-3 Battery
Shut-down
from prior FIR

Inspection Photos
Location Name: KNOX-65N67W /3SWNE
Location #: 331406



Photo #3
Knox 32-3 Unmarked Tank
Contents / Capacity NOT posted
from prior FIR



Photo #4
Knox 32-3 Unmarked Tank
Contents / Capacity NOW posted
Produced H2O tank