

PIT STATUS EVALUATION FORM

Facility ID: 115087

Pit Name: CHAMPLIN 569 AMOCO "A" 1

Duplicate Record(s) Pit #

115155 through 115158



Legend

- Database Pit Location
- Producing Well
- Shut In Well
- Temp Aban Well
- Abandoned Well
- Dry & Aban Well
- Injection Well
- Other Well Status



1:6,000




Image Source:
 USDA National Agricultural Imagery
 Program (NAIP), 2006

S.S. PAPADOPOULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: OLMSTEAD OIL CO
 T: 6S R: 62W Sec: 5 QQ: NESE 6th Meridian
 Latitude: 39.555037 Longitude: -104.349772 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

- Active**
 - Form 15: Pit Permit (1981) new Assoc. Well Seq No(s) _____
 - Other documentation _____
 - Aerial photo verification _____
- Closed**
 - Form 27: Remediation Workplan _____
 - Form 4: Sundry Notice _____
 - Rule 903a.(2)B _____
 - Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) 06303 PA (11-13-1995)
 - Other documentation FIR # 444651 (9-25-1996)
- Abandoned**
 - Possible un-reclaimed pit(s) or adverse conditions, no closure docs
 - Site Visit
- Unknown**
 - No Site Visit
 - Add'l Review

Notes: LIF (1981) 10'x10' pit. FIR (1996) "Final P&A inspection & Well plugged and location restored"