

Inspection Photos

Location Name: HG DURAN 34-27 AND TR

API #: 05-071-08043

Insp. Doc. # 695100362



Colorado Oil & Gas Conservation Commission
37.13887, -104.87146, 2113.0m, 194°
2019/03/15 15:50:49

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.13875, -104.87111, 2124.0m, 235°
2019/03/15 15:51:17

PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: HG DURAN 34-27 AND TR
API #: 05-071-08043
Insp. Doc. # 695100362

Report Date 1/30/18 2:46 PM
Section 1 - Meter
Device ID 100108043
Location HG DURAN 34-27

Colorado Oil & Gas Conservation Commission
37.13871, -104.87102, 2122.0m, 313°
2019/03/15 15:53:59

PHOTO 3: CALIBRATION PAST DUE

Report Date 1/30/18 3:01 PM
Section 1 - Meter
Device ID 100108218
Location HG DURAN 34-27 TR

Calibration
Collect

Tap Size 0.625
Tap Type SP Tap Location
SP Tap Location 114°

Colorado Oil & Gas Conservation Commission
37.13874, -104.87086, 2118.0m, 114°
2019/03/15 15:54:17

PHOTO 4: CALIBRATION PAST DUE

Inspection Photos

Location Name: HG DURAN 34-27 AND TR

API #: 05-071-08043

Insp. Doc. # 695100362



PHOTO 5: IMPACTIED SOIL NEAR COMPRESSOR

