

Diamond Operating, Inc, Ward Unit 44-3
121-10652

Inspection #688304098

3/12/2019

Routine Inspection

A photograph of a wellhead in a desert landscape. The wellhead is a metal structure with a blue cap and a red valve. To its right is a black sign with white text. The sign is supported by a black metal frame. The ground is sandy and cracked, with sparse, dry vegetation in the background. The sky is clear and blue.

DIAMOND OPERATING, INC.

WARD 44-3 WELL
SE SE SEC.03-T2S-R54W
FOR INFORMATION: 303-494-4420
IN CASE OF EMERGENCY: DIAL 911

03.12.2019



DIAMOND OPERATING, INC.
WARD 44-3 WELL
SE SE SEC.03-T2S-R54W
FOR INFORMATION: 303-494-4420
IN CASE OF EMERGENCY: DIAL 911

03.12.2019



03.12.2019



03.12.2019



03.12.2019



DIAMOND OPERATING, INC.
WARD TANK BATTERY
SE SE SEC.03-T2S-R54W
WASHINGTON COUNTY
NORTH OF LONDON, CO ON RD S TO RD 21, WEST
ON 21 TO RD R, NORTH ON R TO RD 23, EAST 1 MI
FOR INFORMATION: 303-494-4420
24 Hour Contact: 888-992-9282 or In Case of Emergency Call 911

03.12.2019



50363 SPEC 11828 11809
PRODUCED CRUDE OIL
500 BBLS

1 3 0

819
1118
UNPRODUCED CRUDE OIL
500 BBLS

1 3 0

03.12.2019



03.12.



03.12.2019



03.12.2019



03.12.2019



03.12.2019



03.12.2019



PRODUCED
WATER
10 BBL



03.12.2019



PRODUCED
WATER
500 BBLs

03.12.2019



03.12.2019

DIAMOND OPERATING INC.
WARD UNIT-OUTFALL 001
CDPS DISCHARGE FACILITY NUMBER
COG **CDPHE PERMIT #: COG840019**
COLORADO WATER QUALITY CONTROL DIVISION

03.12.2019



03.12.2019



03.12.2019



03.12.2019



03.12.2019