

PIT STATUS EVALUATION FORM

Facility ID: 115105

Pit Name: WHITEHEAD 41-7 4

☐ Duplicate Record(s) Pit #



Legend

- Database Pit Location
- Producing Well
- + Shut In Well
- ~ Temp Aban Well
- X Abandoned Well
- ⊗ Dry & Aban Well
- ♦ Injection Well
- Other Well Status



1:6,000
0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery
Program (NAIP), 2006

S.S. PAPADOPOULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: CHAMPLIN PETROLEUM COMPANY
T: 6S R: 62W Sec: 7 QQ: CNE 6th Meridian
Latitude: 39.545797 Longitude: -104.370982 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

- ☐ **Active**
- ☐ Form 15: Pit Permit (1982) existing Assoc. Well Seq No(s) _____
- ☐ Other documentation _____
- ☐ Aerial photo verification _____
- ☒ **Closed**
- ☐ Form 27: Remediation Workplan _____
- ☐ Form 4: Sundry Notice _____
- ☐ Rule 903a.(2)B _____
- ☒ Evidence pit(s) existed, no closure docs & well not PR, AC or SI 06352 DA (7-23-81)
- Well API Seq #(s) 06358 PA (4-28-87) 06363 PA (4-23-87) 06361 PA (4-28-87)
- ☒ Other documentation WSIF # 436804 (1987), WSIF # 436785 (4-28-87)
- ☐ **Abandoned** ☐ Possible un-reclaimed pit(s) or adverse conditions, no closure docs ☐ Site Visit
- ☐ **Unknown** ☐ No Site Visit
- ☐ Add'l Review

Notes: WSIF # 436628, # 436804, # 436785 (1987) Pit backfilled.

FIR # 447394 (11-8-85) No visible sign of API seq No 06352