

Inspection Photos
Location Name: Ludwig #3
Facility ID: 444255



Photo 1 & 2 – Windblown dust from cuttings directly south of facility on adjacent neighbors property- areas of accumulation extend up to 1,000 feet into field. Full impacts to be defined upon snow melt to minimize damage to crops.

Inspection Photos
Location Name: Ludwig #3
Facility ID: 444255



Photo 3 – Windblown dust in area where snow has melted.

Photo 4 – Members of PDC Land and Environmental teams met with COGCC and landowner to the south to discuss environmental response.

Inspection Photos
Location Name: Ludwig #3
Facility ID: 444255



Photo 5 – Windblown dust on ice in the Spear Canal (canal not flowing). Spill cleanup pending permission from owners of canal.

Photo 6 – Sample location.