

Inspection Photos
Location Name: Cosslett Unit D #1
Location ID: 336071



Photo 1 WH and PU




Photo 2 stained soil and Mechanical issues (packing appears to be leaking).