

Inspection Photos

3/18/2019

Operator: VERDAD RESOURCES LLC # 10651

Location ID: 441041

Inspection Doc. Number: 682504606

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the east end of the pad, facing south. Photos 1-4 provide an overview of the location from south, southwest, northwest to north. Photos show interim reclamation has not been conducted on the location; areas of the location not reasonably needed for production have not been reclaimed.



Photo 2: See comments under photo 1.

Inspection Photos
Operator: VERDAD RESOURCES LLC # 10651
Location ID: 441041



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.



Photo 5: Photo taken from the southeast corner of the pad, facing west. See comments under photo 1.



Photo 6: Photo taken from the southeast corner of the pad, facing north. See comments under photo 1.



Photo 7: Photo taken from the south end of the pad, facing west. Photo shows undesirable weedy plant species (Russian thistle, *Salsola sp.*) has been allowed to establish throughout the location.



Photo 8: Photo taken from the southwest corner of the pad, facing north. See comments under photo 1.



Photo 9: Photo taken from the southwest corner of the pad, facing east. See comments under photo 1.



Photo 10: Photo taken from the northwest corner of the pad, facing east. See comments under photo 1.



Photo 11: Photo taken from the northwest corner of the pad, facing south. See comments under photo 1.



Photo 12: Photo taken from the topsoil stockpile on the north end of the pad, facing east. Photos 12-15 provide an overview of the location from east, southeast, southwest to west. Photos show interim reclamation has not been conducted on the location; areas of the location not reasonably needed for production have not been reclaimed.



Photo 13: See comments under photo 12.



03.18.2019

Photo 14: See comments under photo 12.



Photo 15: See comments under photo 12.



Photo 16: Photo of the four (4) producing wells on the location. All remaining permitted wells on the location have been abandoned.