

# Inspection Photos

3/18/2019

Operator: NOBLE ENERGY INC - 100322

Location ID: 431312

Inspection Doc. Number: 682504616

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the north end of the location, facing west. Photos 1-4 provide an overview of the location from west, southwest, southeast to east. Photos 5-8 show interim reclamation in process.



**Photo 2:** See comments under photo 1.



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 431312



**Photo 5:** Photo of PR well on location.