


PIT STATUS EVALUATION FORM

Facility ID: 115132

Pit Name: GAEDE 1-34

Duplicate Record(s) Pit #



Legend

- Database Pit Location
- Producing Well
- + Shut In Well
- ⊗ Temp Aban Well
- ⊘ Abandoned Well
- ⊙ Dry & Aban Well
- ◆ Injection Well
- Other Well Status



Image Source:
USDA National Agricultural Imagery
Program (NAIP), 2006

S.S. PAPANOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: CHURCHILL ENERGY INC
T: 8S R: 57W Sec: 34 QQ: NENE 6th Meridian
Latitude: 39.314963 Longitude: -103.754431 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

- Active** Form 15: Pit Permit NA Assoc. Well Seq No(s) _____
 Other documentation _____
 Aerial photo verification _____
- Closed** Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
Well API Seq #(s) 06505 PA (8-15-1998)
 Other documentation WSIF # 471804 (10-18-1985)
- Abandoned** Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: WSIF (1985) pits backfilled & site clean