

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08698
Date: 2-18-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern project area from the northeastern edge facing northwestward.



Photo 3. View of unmarked rig anchor within the eastern project area.



Photo 4. View of erosional channels eroding the eastern project area.