

Inspection Photos

Location Name: ANDERSON-66N66W /10SWNE

Location #: 305912



Photo #1

Anderson 32-10 (05-123-23661) Wellsite
Temporarily Abandoned | TA
Unused Equipment
from prior FIR



Photo #2

Anderson 32-10 Wellsite
Temporarily Abandoned | TA
Unused Equipment - Removed



Inspection Photos

Location Name: ANDERSON-66N66W /10SWNE

Location #: 305912



Photo #3

Anderson 31-10, 32-10, 42-10 Battery site

from prior FIR

