

Inspection Photos
Location Name: ANDERSON-66N66W /10SENE
Location #: 306516



Photo #1
Anderson 42-10 (05-123-24819) Wellsite
Temporarily Abandoned | TA
Unused Equipment
from prior FIR



Photo #2
Anderson 42-10 Wellsite
Temporarily Abandoned | TA
Unused Equipment - Removed

Inspection Photos

Location Name: ANDERSON-66N66W /10SENE

Location #: 306516



Photo #3

Anderson 31-10, 32-10, 42-10 Battery site

from prior FIR



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources