

# Final Reclamation Inspection

March 15, 2019

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 330787

Inspection Document #: 682404683

Weld County, CO

SESW Section 31 T8N R60W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HILL #31-14-7  
Location ID: 330787



**Photo 1.** Photo taken from the entrance of the location, facing North. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch. However, straw mulch has already blown off portions of the PA location, as shown above.

Inspection Photos  
Location Name: HILL #31-14-7  
Location ID: 330787



**Photo 2.** Photo taken along a portion of the access road, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: HILL #31-14-7  
Location ID: 330787



**Photo 3.** Photo taken along a portion of the access road, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: HILL #31-14-7  
Location ID: 330787



**Photo 4.** Photo taken of the well pad, facing Northeast. See comments under Photo 1.