

Laramie Energy LLC
Api # 05-077-08230
Inspection # 675002032



Photo of location

Laramie Energy LLC
Api # 05-077-08230
Inspection # 675002032



Photo of Wellhead

Laramie Energy LLC
Api # 05-077-08230
Inspection # 675002032



Photo of Tank Battery

Laramie Energy LLC
Api # 05-077-08230
Inspection # 675002032



Truck rack stored by well head



More equipment stored by surface equipment

Laramie Energy LLC
Api # 05-077-08230
Inspection # 675002032



**Unused equipment and storage of land owner equipment
stored on location**



Unused Pipe and fittings left on location

Laramie Energy LLC
Api # 05-077-08230
Inspection # 675002032



Rubbish removed from around surface equipment



Land owner equipment stored around tank